

October 5<sup>th</sup>, 2011

## STATEMENT

We confirm, that the following replacement catalytic converter type 7515K, produced by SITO Gruppo Industriale S.p.A. (S.G.I.), is complying with

- the EC-Directive 97/24/EC Chapter 5, regarding measures to be taken against air pollution

An EC type approval number has been granted by the luxembourgian Ministry for Sustainable Development and Infrastructure, department of Transport, for the following version of the above mentioned catalytic converter type:

| Silencer Version        | Silencer Type approval number                                                              | catalytic converter Version | catalytic converter Type approval number                                                   | Vehicle type                                            | Vehicle Model                   |
|-------------------------|--------------------------------------------------------------------------------------------|-----------------------------|--------------------------------------------------------------------------------------------|---------------------------------------------------------|---------------------------------|
| 7172<br>7173<br>7174    |  0230 ⑨ | 6547K                       |  0387 ⑤ | SD01 – SD01A                                            | HONDA VARADERO 1000             |
| 7172<br>7173<br>7174    |  0230 ⑨ | 6547K                       |  0387 ⑤ | JC32A - SD02 Var.1 Vers.1<br>VTMSD02A – JH2SD01A – SD02 | HONDA VARADERO 1000 i.e.        |
| 7172<br>7173<br>7174    |  0230 ⑨ | 6547K                       |  0387 ⑤ | JC32A - SD02 Var.1 Vers.1<br>VTMSD02A – JH2SD01A – SD02 | HONDA VARADERO 1000<br>ABS i.e. |
| 7172K<br>7173K<br>7174K |  0230 ⑨ | 6547K                       |  0387 ⑤ | SD01 – SD01A                                            | HONDA VARADERO 1000             |
| 7172K<br>7173K<br>7174K |  0230 ⑨ | 6547K                       |  0387 ⑤ | JC32A - SD02 Var.1 Vers.1<br>VTMSD02A – JH2SD01A – SD02 | HONDA VARADERO 1000 i.e.        |
| 7172K<br>7173K<br>7174K |  0230 ⑨ | 6547K                       |  0387 ⑤ | JC32A - SD02 Var.1 Vers.1<br>VTMSD02A – JH2SD01A – SD02 | HONDA VARADERO 1000<br>ABS i.e. |



Gilles AST  
Expert Technique